

Mount McKinley Headquarters, Electric Light Plant
(Mount McKinley Headquarters, Ranger Office)
(Mount McKinley Headquarters, Building No. 110)
Denali National Park and Preserve
McKinley Station
Yukon-Koyukuk Division
Alaska

HABS No. AK-35-L

*HABS
AK,
23-MCKIN,
1-L-*

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA
REDUCED COPIES OF MEASURED DRAWINGS

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, DC 20013-7127

HABS
AK,
23-MCKIN,
1-L-

ARCHITECTURAL DATA FORM

STATE ALASKA	COUNTY YUKON-KOYUKUK DIVISION	TOWN OR VICINITY MCKINLEY STATION
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Mount McKinley Headquarters (National Park Service files)		HABS NO. AK-35 L
SECONDARY OR COMMON NAMES OF STRUCTURE Electric Light Plant; Ranger Office; Building #110		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) Denali National Park & Preserve		
DATE OF CONSTRUCTION (INCLUDE SOURCE) 1930-1931 (NPS files)		ARCHITECT(S) (INCLUDE SOURCE)
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) This building typifies more than all others in the park the continually changing use of space. Since its construction it has served at least seven different functions. Originally housed a generator; then garage; food storage cache; electric shop; naturalist office; storage the Upfront office for east district ranger.		
STYLE (IF APPROPRIATE) Rustic		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) log, concrete		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) rectangle; 14' x 16' one story		
EXTERIOR FEATURES OF NOTE saddle corner notching with sawn and battered log ends		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES replacement of single garage door with pedestrian door, 1940's; sub-floor of planks, 1940's; concrete floor, walls chinked, doors repaired and building rewired, 1953, reseating of corrugated tin roof with wood shakes and exterior walls painted recently.		
PRESENT CONDITION AND USE East district ranger office ; Good condition		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) NPS files; see Bibliography HABS No. AK-35		
COMPILER, AFFILIATION Sandra M. Faulkner, Historian, National Park Service		DATE June 26, 1986